

Subject Property:

11344 Coloma Rd, Gold River, CA 95670, USA

Engaged By:


Client Name: Dev Team

Client Company: DEV_STAGING

Client Address: 123 Test Street, Test City, CA 12345

Order Number: 22D01-33993-829 Date Engaged: 4/1/22 Report Engaged: 4/1/22






SUBJECT PROPERTY: 11344 Coloma Rd, Gold River, CA 95670, USA APN: 06901100090000 CLIENT COMPANY: DEV_STAGING CLIENT NAME: Dev Team



ORDER: 22D01-33993-829





ADDRESS: 11344 Coloma Rd, Gold River, CA 95670, USA

Regulatory Summary | Subject Property

	SITE NAME	ADDRESS	DIST. DIR ELEV DIFF	POINTS OF INTEREST	POTENTIAL RISK
Ŷ	SACRAMENTO COUNTY FIRE DEPT.	11344 Coloma Rd, Gold River, CA 95670, USA		California Hazardous Material Incident Report System (CHMIRS) <u>Click for Details</u>	ELEVATED

CONFIDENTIAL

	SITE NAME	ADDRESS	DIST. DIR ELEV DIFF	POINTS OF INTEREST
₿	CHAD EVANS CIELO UNIDOS	2323 Gold River Rd, Gold River, CA 95670, USA	0' SW	California Hazardous Material Incident Report System (CHMIRS), STATUS : Notified Date : 5/4/1995
	EAGLE AUTOMOTIVE KELLY REIGER			Hazardous Waste Manifest Data (6x)
	METRICS MIKE RICK S AUTOMOTIVE RIP BODY SHOP SACRAMENTO FD			Registered Waste Tire Haulers
ę	BELLISSIMO MOTOR DBA MUGELLO MOTORS GAIL PHILLIPS GARRETT'S ELECTRONIC RECYCLING KELLY GRIFFITH CUSTOMS KOMPUTER KEVIN KRASS COMMERICAL MANAGEMENT COMPANY MARANGI'S PAINTING & DECORATING NOR CAL COOLING TOWER SERVICES INC UNION PAINTING & DECORATING	2335 Gold River Rd, Gold River, CA 95670, USA	0' SW	Hazardous Waste Manifest Data (6x)
_	SACRAMENTO WATERPROOFING IND. INC. VALLEY PAINTING &	D. INC. 11300 Coloma Rd A5, Gold River, CA 95670, USA	0' W	Facility Registry Service/Facility Index, STATUS : Registry ID : 110002849696
P	DECORATING			Hazardous Waste Manifest Data (3x)
	VALLY PAINTING & DECORATING			RCRA Small Quantity Generators List, STATUS : EPA Handler ID : CAD983589755

	SITE NAME	ADDRESS	DIST. DIR ELEV DIFF	POINTS OF INTEREST
	BODY MECHANICS BODY MECHANICS INC. CAMELLIA CITY LANDSCAPE MNGMT CARLYINE GOLF CARS CARLYNE GOLF CARS M&M BODY MECHANICS INC	2347 Gold River Rd # G, Rancho Cordova, CA 95670, USA		California Environmental Reporting System (CERS) Hazardous Waste Sites (2x)
				Facility Registry Service/Facility Index, STATUS : Registry ID : 110066402949
				Facility Registry Service/Facility Index, STATUS : Registry ID : 110070447908
P			0' S	Facility Registry Service/Facility Index, STATUS : Registry ID : 110070467426
	MASTER MECHANICS MORISON MARINE			Hazardous Waste Manifest Data (6x)
	MORRISON MARINE			RCRA Non-Generators: , STATUS : EPA Handler ID : CAL000171075
	VERIZON WIRELESS COLOMA ROAD			RCRA Non-Generators: , STATUS : EPA Handler ID : CAL000304681
				RCRA Non-Generators: , STATUS : EPA Handler ID : CAL000467976
	1X COAN EQUIPMENT COMPANY			California Environmental Reporting System (CERS) Hazardous Waste Sites
	ARONSON CONSTUCTORS ARONSON ENGINEERING INC ARONSON TRANSPORTATION INC COAN EQUIPMENT CO INC COAN EQUIPMENT CO., INC. COAN PROPERTY GROUND ZERO AUTO BODY INC KLEARY MASONRY INC KLEARY MASONRY INC KLEARY MASONRY, INC. KVAERNER DAVY ARONSON, INC. RADIAN ENGINEERING WILL BONO ENVIRONMENTAL; SERVICES	11297 Coloma Rd A, Gold River, CA 95670, USA	83' NW	Facility Registry Service/Facility Index, STATUS : Registry ID : 110002905438
				Facility Registry Service/Facility Index, STATUS : Registry ID : 110009551797
				Hazardous Waste Manifest Data (6x)
F				Historical Hazardous Substance Storage Container Information - Facility Summary
Y				Historical Hazardous Substance Storage Information Database
				Historical Hazardous Waste Manifest Data
				RCRA Non-Generators: , STATUS : EPA Handler ID : CAR000001925
				RCRA Non-Generators: , STATUS : EPA Handler ID : CAR000001933
				Statewide Environmental Evaluation and Planning System, STATUS : C C : I34-000-40343, Status : INACTIVE, Tank ID : 000004 - 000001 - 000003 - 000002
ø	GOLD RIVER RACQUET CLUB	2201 Gold Rush Dr, Gold River, CA 95670, USA	94' N	California Environmental Reporting System (CERS) Hazardous Waste Sites
				Facility Registry Service/Facility Index, STATUS : Registry ID : 110065582729
P	CHP	Coloma Rd & Gold River Rd, Gold River, CA 95670, USA	331' W	California Hazardous Material Incident Report System (CHMIRS), STATUS : Notified Date : 3/8/1995
	1X COUNTY OF	GOLD RIVER RD COLOM RD	361' W	Hazardous Waste Manifest Data
Ŷ	SACRAMENTO			Historical Hazardous Waste Manifest Data

	SITE NAME	ADDRESS	DIST. DIR ELEV DIFF	POINTS OF INTEREST
9	GZ PRODUCTS	2300 Gold River Rd, Gold River, CA 95670, USA	364' W	CALSITES Database
	AMERICAN BUILDING PRODUCTS			California Environmental Reporting System (CERS) Hazardous Waste Sites (2x)
	AT&T MOBILITY - LOWER SUNRISE (9706) AT&T MOBILITY - LOWER SUNRISE (USID9706) GOLD RIVER MOTORSPORTS			Delisted County Records (2x)
				Facility Registry Service/Facility Index, STATUS : Registry ID : 110055806953
				Facility Registry Service/Facility Index, STATUS : Registry ID : 110066470795
Ý	HOWARD S WRIGHT	11267 Coloma Rd, Gold River, CA 95670, USA	367' W	Hazardous Waste Manifest Data (5x)
	NORCAL COOLING TOWER SERVICE INC			Historical Hazardous Substance Storage Container Information - Facility Summary
	SPRINT CELL SITE FN04XC068 SUPERIOR BOAT REPAIR & STORAGE INC THE AIR WORKS WELD TECH			Historical Hazardous Substance Storage Information Database
	1X FOREMOST INTERIORS INC FOREMOST INTERIORS FOREMOST INTERIORS INC FOREMOST INTERIORS INC. FOREMOST INTERIORS, INC	2318 Gold River Rd, Rancho Cordova, CA 95670, USA	448' SW	Facility Registry Service/Facility Index, STATUS : Registry ID : 110000485760
				Hazardous Waste Manifest Data
(Historical Hazardous Substance Storage Container Information - Facility Summary
Ŷ				Historical Hazardous Substance Storage Information Database
				Historical Hazardous Waste Manifest Data
	WAREHOUSE PAINT			RCRA Non-Generators: , STATUS : EPA Handler ID : CAC003154827
				Toxics Release Inventory (TRI) Program
Y		COLONAGOLD RUSH	459' NE	Historical California Hazardous Material Incident Report System (CHMIRS)
P	GOLD RIVER TIRE & AUTO SERV. GOLD RIVER TIRE & AUTO SVC IN	2322 Gold River Rd, Rancho Cordova, CA 95670, USA	473' SW	Hazardous Waste Manifest Data

	SITE NAME	ADDRESS	DIST. DIR ELEV DIFF	POINTS OF INTEREST
?	1X CUSTOM-PAINT ENGINE BETTER BAYS BODY SHOP BETTER DAYS BODY & PAINT SHOP BODY BEAUTIFUL AUTO RESTORATIO EAGLE AUTO BODY J & J AUTOMOTIVE J&J AUTOMOTIVE KING FILTER RECYCLING SERVICE RANCHO TOW STINSON VENTURES TOMZ KUSTOMS/TOM LEMANS KUSTOMS WELD TECH	2340 Gold River Rd m, Gold River, CA 95670, USA	494' SW	Delisted County Records Hazardous Waste Manifest Data (10x) Historical California Hazardous Material Incident Report System (CHMIRS)

8	11344 Coloma Rd, Gold River,	CA 95670, USA (id : 821862353) <u>Return to Parent</u>		
ld	821862353			
Source	CHMIRS			
Source Description		aterial incidents, spills, and releases from the California Hazardous Material Incident Report s been made available by the California Office of Emergency Services (OES).		
Company Name	Sacramento County Fire Dept.			
Address	11344 Colona Road, Rancho C	Cordova CA		
Latitude/Longitude	38.62100462/-121.26047173			
Distance	24.05 feet, 0.0 miles, 7.33 mete	ers		
Elevation	117.95 feet, 35.95 meters			
Direction	NW			
Control No	08-3177			
County	Sacramento County			
Year	2008			
URL	https://w3.calema.ca.gov/operational/malhaz.nsf/f1841a103c102734882563e200760c4a/66d6e2a9fa31b2c88825743c0064381 1?OpenDocument			
California Hazardous Material Incident Report System (as Of 2006 To 2015)	1 Substance	Sewage		
	1 Measure	Gal(s)		
	1 Quantity	UNK		
	1 Туре	SEWAGE		
	Incident Date	5/1/2008		
	Incident Time	1007		
	Spill Site	Waterways		
	No of Injuries	0		
	No of Fatals	0		
	No of Evacs	0		
	Cleanup	Unknown		
	Site	storm drain		
	Water	Yes		
	Water Way	storm drain		
	City	Rancho Cordova		
	County	Sacramento County		
	Admin Agency	Sacramento County Environmental Mgmt.		
	Notification Area	AA/CUPA,DFG-OSPR,DTSC,RWQCB,US EPA,USFWS,COASTAL COM,LANDS,PARKS & REC,USCG		

	Location	11344 Colona Road
	Description	The caller is reporting sewage in a parking lot that is spilling into a storm drain. The sewage is spilling at the rate of 10-20 gallons per minute.
Spill Report View	Туре	SEWAGE
	Document Title	SPILL Report
	Creation Date	05/01/2008 11:14 AM
	Spill Site	Waterways
	Туре	SEWAGE
	Document Title	Cal OES-Update
	Creation Date	05/01/2008 03:17 PM
	Туре	SEWAGE
	Document Title	Cal OES-Update
	Creation Date	05/01/2008 12:46 PM
Oes Hazardous Materials Spill Update	Occurrence Date	05/01/2008
	Notify Date	05/01/2008
	Notify Time	1114
	1 Substance	Sewage
	1 Qty Amount	UNK
	1 Measure	Gal(s)
	1 Туре	SEWAGE
	OP Area	Sacramento County
	Pers Notifying CA OES Agency	Sacramento County Fire Dept.
	Fax Notifi List	AA/CUPA, DFG-OSPR, DTSC, RWQCB, US EPA, USFWS, COASTAL COM, LANDS, PARKS & REC, USCG
	Administering Agency	Sacramento County Environmental Mgmt.
	Doc URL	https://w3.calema.ca.gov/operational/malhaz.nsf/f1841a103c102734882563e200760c4a/b518e 85c781e98e88825743c006ca13a?OpenDocument
	Situation Update	The caller is advising that the sewage is spilling at a rate of 3 gallons a minutes. The sewage is contained in the storm drain. 165 gallons of sewage spilled into an unknown creek.
	ERIS_PARENT_ID	3155123002
	Occurrence Date	05/01/2008
	Notify Date	05/01/2008
	Notify Time	1114
	1 Substance	Sewage
	1 Qty Amount	UNK
	1 Measure	Gal(s)

	1 Туре	SEWAGE
	OP Area	Sacramento County
	Pers Notifying CA OES Agency	Sacramento County Fire Dept.
	Fax Notifi List	AA/CUPA, DFG-OSPR, DTSC, RWQCB, US EPA, USFWS, COASTAL COM, LANDS, PARKS & REC, USCG
	Administering Agency	Sacramento County Environmental Mgmt.
	Doc URL	https://w3.calema.ca.gov/operational/malhaz.nsf/f1841a103c102734882563e200760c4a/0e955 36cd5e2a7e88825743c007a6906?OpenDocument
	Situation Update	The total amount spilled was 540 gallons, with 160 gallons in the waterway.
	ERIS_PARENT_ID	3155123003
Oes Hazardous Materials Update Quantities	Measure	Gal(s)
	ERIS_PARENT_ID	3155001399
	Measure	Gal(s)
	ERIS_PARENT_ID	3154982849
Hazardous Materials Spill Report	Date	05/01/2008
	Time	1114
	Incident Date	05/01/2008
	Incident Time	1007
	Water Involved	Yes
	Waterway	storm drain
	RWQCB Unit	5B
	1 Substance	Sewage
	1 Qty	=
	1 Amount	UNK
	1 Measure	Gal(s)
	1 Туре	SEWAGE
	Control Cal OES	08-3177
	Cleanup By	Unknown
	2 Qty	=
	3 Qty	=
	Incident Location	11344 Colona Road
	Agency	Sacramento County Fire Dept.
	Admin Agency	Sacramento County Environmental Mgmt.
	Header Unknown	SACRAMENTO METROPOLITAN AQMD
	Site	Waterways

Description	The caller is reporting sewage in a parking lot that is spilling into a storm drain. The sewage is spilling at the rate of 10-20 gallons per minute.
ERIS_PARENT_ID	3155123001

REPORT USAGE

THIS **ENVIROPRESCREEN** REPORT HAS BEEN PREPARED FOR THE EXCLUSIVE USE OF THE CLIENT. USE BY ANY OTHER PARTY IS STRICTLY PROHIBITED WITHOUT THE WRITTEN AUTHORIZATION OF CRETELLIGENT. USE OF THIS **ENVIROPRESCREEN** REPORT BY THE CLIENT IS SUBJECT TO THE TERMS, CONDITIONS, AND LIMITATIONS BELOW AND/OR IN ACCORDANCE WITH CRETELLIGENT'S TERMS & CONDITIONS AND/OR ENGAGEMENT AGREEMENT FOR THIS **ENVIROPRESCREEN** REPORT. THIS **ENVIROPRESCREEN** REPORT IS VALID FOR 30 DAYS FROM THE DATE OF COMPLETION.

LIMITATIONS OF LIABILITY

TO CONDUCT THE LIMITED SCOPE OF SERVICES IN PREPARATION OF THIS ENVIROPRESCREEN REPORT FOR THE SUBJECT PROPERTY. CRETELLIGENT CONSULTED INFORMATION FROM SOURCES THAT ARE COMMON AND STANDARD TO THE COMMERCIAL REAL ESTATE DUE DILIGENCE INDUSTRY. CRETELLIGENT BELIEVES THESE SOURCES IS RELIABLE AND TRUE AND CORRECT. HOWEVER, CRETELLIGENT HAS MADE NO INDEPENDENT INVESTIGATION VERIFYING ACCURACY OR COMPLETENESS OF THE SOURCE INFORMATION RELIED UPON TO PREPARE THIS ENVIROPRESCREEN REPORT AND CRETELLIGENT CANNOT AND DOES NOT WARRANT OR GUARANTEE THAT THE INFORMATION PROVIDED BY THESE OTHER SOURCES IS ACCURATE OR COMPLETE. CRETELLIGENT UNDERTAKES NO RESPONSIBILITY FOR THE ACCURACY OF SUCH SOURCE INFORMATION. SPECIALIZED EXPERIENCE OR KNOWLEDGE OF THE CLIENT, SUBJECT PROPERTY PURCHASE PRICE INFORMATION, SUBJECT PROPERTY DEED RESTRICTIONS OR LAND USE LIMITATIONS. SUBJECT PROPERTY INSTITUTIONAL CONTROLS OR ENGINEERING CONTROLS, AND/OR SUBJECT PROPERTY ENVIRONMENTAL LIEN INFORMATION WERE NOT PROVIDED BY THE CLIENT TO CRETELLIGENT. IN CONDUCTING THE LIMITED SCOPE OF SERVICES DESCRIBED IN THIS ENVIROPRESCREEN REPORT. CERTAIN SOURCES OF INFORMATION AND PUBLIC RECORDS WERE NOT AND WILL NOT BE REVIEWED BY CRETELLIGENT. IT SHOULD BE RECOGNIZED THAT POTENTIAL ENVIRONMENTAL POINTS OF INTEREST MAY BE DOCUMENTED IN SUCH OTHER SOURCES AND RECORDS. NEITHER CLIENT'S ENGAGEMENT OF CRETELLIGENT TO CONDUCT THIS ENVIROPRESCREEN REPORT, NOR THE COMPENSATION FOR IT, IS CONTINGENT UPON THE RESULTS OF THIS ENVIROPRESCREEN REPORT, CRETELLIGENT HAS NO PERSONAL INTEREST IN OR CONCERNING THE SUBJECT MATTER OF THIS ENVIROPRESCREEN REPORT OR ANY PARTIES WHO MAY BE PARTY TO FINANCIAL TRANSACTIONS INVOLVING THE SUBJECT PROPERTY COVERED BY THIS ENVIROPRESCREEN REPORT. THIS ENVIROPRESCREEN REPORT SHALL BE GOVERNED BY AND CONSTRUED IN ACCORDANCE WITH THE LAWS OF THE STATE OF CALIFORNIA (WITHOUT REGARD TO ITS CONFLICTS OF LAWS PROVISIONS). BY ORDERING THIS ENVIROPRESCREEN REPORT, CLIENT AGREES THAT SACRAMENTO COUNTY CALIFORNIA SHALL BE THE VENUE OF ANY ACTION REGARDING THIS ENVIROPRESCREEN REPORT.

NO WARRANTY EXPRESSED OR IMPLIED IS MADE CONCERNING THIS **ENVIROPRESCREEN** REPORT. CRETELLIGENT SPECIFICALLY DISCLAIMS THE MAKING OF ANY SUCH WARRANTIES, INCLUDING MERCHANTABILITY OR FITNESS FOR A PARTICULAR USE, PURPOSE, OR RELIANCE. ALL RISK IS ASSUMED BY THE CLIENT. IN NO EVENT SHALL CRETELLIGENT BE LIABLE TO ANYONE, WHETHER ARISING OUT OF ERRORS OR OMISSIONS, NEGLIGENCE, ACCIDENT OR ANY OTHER CAUSE, FOR ANY LOSS OF DAMAGE, INCLUDING SPECIAL, INCIDENTAL, CONSEQUENTIAL, OR EXEMPLARY DAMAGES. THE CLIENT ACCEPTS THIS **ENVIROPRESCREEN** REPORT "AS IS". ANY ANALYSES, ESTIMATES, RATINGS, ENVIRONMENTAL RISK RATINGS, LEVELS, RISK CODES, OR OTHER INFORMATION PROVIDED IN THIS **ENVIROPRESCREEN** REPORT ARE FOR ILLUSTRATIVE PURPOSES ONLY, AND ARE NOT INTENDED TO PROVIDE, NOR SHOULD THEY BE INTERPRETED AS PROVIDING, ANY FACTS REGARDING, OR PREDICTIONS OF, ANY ENVIRONMENTAL RISK FOR ANY PROPERTY. THE **ENVIROPRESCREEN** REPORT IS NOT A SUBSTITUTE FOR A PHASE I ENVIRONMENTAL SITE ASSESSMENT ("ESA") AND CRETELLIGENT'S PREPARATION OF, NOR CLIENT'S OBTAINING OF, THIS **ENVIROPRESCREEN** REPORT SHALL NOT MEET THE REQUIREMENTS FOR PERFORMING AN ESA FOR THE PURPOSE OF QUALIFYING FOR CERTAIN LIABILITY PROTECTIONS UNDER THE COMPREHENSIVE ENVIRONMENTAL RESPONSE, COMPENSATION AND LIABILITY ACT (CERCLA). ADDITIONALLY, WITHOUT FURTHER CONFIRMATION BY COMPLETING A PHASE I ESA, PERFORMED IN ACCORDANCE WITH ASTM E1527-13. THE CONDITIONS AFFECTING THE SUBJECT PROPERTY ARE UNKNOWN AND CRETELLIGENT MAKES NO REPRESENTATIONS REGARDING ANY SUCH CONDITIONS.